


Interstate Designation Issues



VERTICAL CLEARANCE DEFICIENCIES

Disclaimer Statement:
This is not a proposal

This is a display of vertical clearance deficiencies for bridge structures if strict Interstate standards were applied.
Future negotiations with the U.S. Department of Transportation may eliminate some or all of the listed locations.



Tag #	PM	Location Description
32	28.17	Le Grand Avenue OC
33	26.58	N99 & 233 Connector
34	23.77	Avenue 24 OC
35	23.06	Califa UP Pp
36	22.73	N99-W152 Connector Sep
37	12.75	Avenue 16 OC
38	12.13	Cleveland Avenue OC
39	12.12	Cleveland Avenue OC Pp
40	11.01	W Fourth Street OC
41	10.84	W Yosemite Ave OC
42	10.76	W Sixth Street OC
43	10.27	Route 145/99 Seperation
44	9.74	South Madera OC
45	R0.99	Avenue 7 OC

